

Work Order ID 63368



Page 1

Thursday, October 28, 2010 10:02:07 AM

Item ID: D3595-063-395

Accept



Setup Start



Revision ID:

Item Name: RUBBER CUSHION

Stop



Start Date: 10/28/2010 Start Qty: 40.00



Cust Item ID:

Required Date: 11/18/2010 Req'd Qty: 40.00



Customer:

Reference:

Approvals:	Process Plan:	<i>K</i>	Date: 10-10-28	Tooling:	_____	Date: _____	Run Start	Barcode
	QC:	_____	Date: _____	SPC (Y/N):	_____	Date: _____	Stop	Barcode

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
--------------------------------	--------------------------	----------------------	---------	--------	--------------	---------------	---------------	------------------	----------------

Draw Nbr	Revision Nbr	
----------	--------------	--

D3595	Rev. A	
-------	--------	--

100	0.00	10-11-2	PRO
-----	------	---------	-----



FLOW WATER JET

Waterjet

Memo 0.00

FLOW CNC Waterjet

1-Cut as per Dwg D3595 Dwg Rev: **A** Prog Rev: **A** 2-
Deburr if necessary

10-11-2

110



QC2- Inspect parts off machine FAI/FAIB 0.00

QC

Quality Control

Memo 0.00

10-11-2

120



QC8- Inspect parts - second check 0.00

QC

Quality Control

Memo 0.00

W10:63368	Perry ChG.	WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
10.11.02	100	ADD DWG NBR & REV TO ESTIMATE		10.11.03		<i>W</i>	

Part No: D3595-063-395 PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Work Order ID 63368

Page 2

Thursday, October 28, 2010 10:02:07 AM

Item ID: D3595-063-395

Accept



Setup Start



Revision ID:

Item Name: RUBBER CUSHION

Stop



Start Date: 10/28/2010 Start Qty: 40.00



Cust Item ID:

Required Date: 11/18/2010 Req'd Qty: 40.00



Customer:

Reference:

Approvals: Process Plan:

Date:

Tooling:

Date:

Run Start



QC:

Date:

SPC (Y/N):

Date:

Stop

Sequence ID/
Work Center IDOperation
DescriptionSet Up/
Run Hours

Tool ID

Tool #

Plan
CodeAccept
QtyReject
QtyReject
NumberInsp.
Stamp

130



Identify as per dwg & Stock Location: X-tubez

0.00

 10 11 02

Packaging

Memo

0.00

Packaging

140



QC21- Final Inspection - Work Order Release

0.00

QC

Memo

0.00

Quality Control

 10/10/02

 MF
10-11-02

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Picklist Print

Page 1

Thursday, October 28, 2010 10:02:11 AM

Work Order ID: 63368



Parent Item: D3595-063-395



Parent Item Name: RUBBER CUSHION

Start Date: 10/28/2010

Required Date: 11/18/2010

Start Qty: 40.00

Required Qty: 40.00

Comments:

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D3595 		Manufactured	No				sf	0.0000	0.0196	0.825263	1.6		HS 10-11-2

Rubber Cushion (per sq ft)

MNE0805.125

103838

77

W/O:		WORK ORDER CHANGES							
DATE	STEP	PROCEDURE CHANGE			By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)							
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector	
			Initial Chief Eng	Action Description Chief Eng	Sign & Date				

NOTE: Date & initial all entries

DART AEROSPACE LTD	Work Order:	63368
Description: RUBBER CUSHION	Part Number:	3595-03-395
Inspection Dwg: D3595 Rev: A		Page 1 of 1

FIRST ARTICLE INSPECTION CHECKLIST

X First Article **X** Prototype

Measured by:	M3
Date:	10-11-2

Audited by:	C
Date:	10/11/02

Prototype Approval:	
Date:	

Rev	Date	Change	Revised by	Approved
A		New Issue	KJ/JLM	


DART

DESIGN <i>PH</i>	DRAWN BY <i>PH</i>	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
CHECKED <i>✓</i>	APPROVED <i>✓</i>	DRAWING NO. D3595	REV. A SHEET 1 OF 1
DATE 07.02.07		TITLE RUBBER CUSHION	SCALE NTS
A	07.02.07	NEW ISSUE	

RELEASED

07.02.14 *✓*

SPECIFICATION CONTROL DRAWING



EG: 0.75" x 4.30" RUBBER CUSHION = D3595-075-430

NOTES

- 1) MATERIAL: BLACK NEOPRENE SHEET, 0.125 THICK, 80 DUROMETER (REF DART SPEC. M-NE080-S.125)
- 2) FINISH: NONE
- 3) ALL DIMENSIONS ARE IN INCHES
- 4) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED

60

Copyright © 2007 by DART AEROSPACE LTD

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries